



STEP DOCTORS

OF THE CAROLINAS

Professional Fiberglass Pool Skimmer Repair

CRACKED SKIMMER BOTTOM?

We Fix It Right — Without Digging

- ✓ No digging
- ✓ No mess
- ✓ No interruption of swim season
- ✓ Done in one day or less

\$800 – \$1,000

depending on the severity of the crack.

We use high-quality marine-grade fiberglass resin and mat — the full professional method, not a temporary epoxy patch.



Average full skimmer replacement costs \$2,500 and up (cutting concrete, pulling the old unit, replumbing, and patching the deck)

828-384-0048

Call today for a quick assessment



stepdoctors.com